


COORDENADAS DE DEPRESION (QUEBRADA SIN NOMBRE)



COORDENADAS DE DEPRESION		
A	563245.18 m E	940824.41 m N
B	563269.58 m E	940829.32 m N
C	563307.54 m E	940830.94 m N
D	563358.21 m E	940825.01 m N

COORDENADAS ZONA DE PROTECCION DE QUEBRADA SIN NOMBRE		
E	563245.27 m E	940842.39 m N
F	563270.00 m E	940846.00 m N
G	563310.64 m E	940848.38 m N
H	563361.63 m E	940840.48 m N