

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

 A photograph showing a dirt road leading into a construction site. The road is marked with several orange traffic cones. On the left, there is a metal fence and a sign. On the right, there is a yellow sign and a red sign. The background shows a hillside covered in dense green trees.	 A photograph of a steep, excavated hillside. The slope is covered in brown soil and has some orange safety fencing at the top. A yellow sign is visible on the slope. The background shows a dense forest.
<p>Foto 1) Garita de entrada</p>  A photograph of a steep, excavated hillside. The slope is covered in brown soil and has some orange safety fencing at the top. A yellow sign is visible on the slope. The background shows a dense forest.	<p>Foto 2) Manejo de taludes</p>  A photograph of a steep, excavated hillside. The slope is covered in brown soil and has some orange safety fencing at the top. A yellow sign is visible on the slope. The background shows a dense forest.
<p>Foto 3) Manejo de taludes</p>  A photograph of a dirt road or construction site. There are some pipes and equipment visible. The background shows a dense forest.	<p>Foto 4) Adecuación del terreno</p>  A photograph of a construction site. In the foreground, there is a large yellow sign with a red border and black text. The sign says "PELIGRO" in large letters, followed by "LINEAS DE ALTA TENSIÓN DISTANCIA BAJA RIESGO ELÉCTRICO" and a lightning bolt symbol. In the background, there are construction workers and equipment.
<p>Foto 5) Tuberías tramos 6b y 7</p>	<p>Foto 6) Tuberías tramos 6b y 7</p>

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

	
<p>Foto 7) Acopio de residuo sólidos</p> 	<p>Foto 8) Acopio de residuo sólidos</p> 
<p>Foto 9) Almacenamiento de residuos sólidos comunes</p> 	<p>Foto 10) Material absorbente en caso de derrames</p> 
<p>Foto 11) Acopio de material oleoso</p>	<p>Foto 12) Maquinaria conforme a la actividad</p>

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

 A photograph showing a construction site with several pieces of heavy machinery, including a red lattice boom crane and a yellow excavator, positioned on a dirt ground. Construction materials like wooden planks and metal sheets are visible in the background.	 A photograph of a construction site with a blue shipping container and a green port-a-potty in the background. In the foreground, there is a row of orange and yellow safety signs and barriers. One sign clearly reads "DESVIO UN SOLO CARRIL" (Single Lane Detour).
Foto 13) Maquinaria conforme a la actividad	Foto 14) Protección de los trabajadores
 A photograph of a dirt road leading through a construction area. To the left, there is a yellow sign with a white arrow pointing right that reads "RUTA DE EVACUACIÓN" (Evacuation Route). The road is bordered by orange traffic cones and some temporary fencing.	 A photograph showing a construction site with orange safety fencing. In the foreground, there is a wooden A-frame signpost with several red and white signs. One prominent sign reads "APAGUE EL MOTOR DEL VEHICULO" (Turn off the vehicle's engine) and "PROHIBIDO OBSTACULIZAR LAS VÍAS DE CIRCULACIÓN" (Prohibited to obstruct traffic routes). Other signs include "PRESIÓN ALTA" (High pressure) and "PRESIÓN BAJA" (Low pressure).
Foto 15) Protección de los trabajadores	Foto 16) Señalizaciones y advertencias
 A photograph of a construction site with a white and red ambulance parked on the left. The vehicle has "AMBULANCIA" and "EMERGENCIA" written on its side. The background shows a dirt road and some greenery.	 A photograph of a construction site with a large orange safety fence in the foreground. Behind the fence, there is a dirt area and some trees. The background shows a dense forest.
Foto 17) Servicio de Ambulancia	Foto 18) Seguridad

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

 A yellow A-frame safety sign stands on a rocky construction site. The sign has a blue header that reads "USO OBLIGATORIO DE EQUIPOS DE SEGURIDAD" and shows icons for hard hats, safety vests, and safety glasses. The body of the sign lists "AUXILIO, CASCO, GUANTES, Lentes, Chaleco".	 An emergency first aid station (Botiquín de Emergencia) is shown. It is a red and white striped metal structure with a red plastic tub inside. A sign on the right side reads "ESTACIÓN DE EMERGENCIA".
<p>Foto 19) Orientación al trabajador</p>  A larger emergency first aid station (Botiquín de Emergencia) is shown inside a wooden shelter. It has red and white striped barriers and a red plastic tub inside. A sign on the right side reads "ESTACIÓN DE EMERGENCIA".	<p>Foto 20) Botiquines de emergencia en campo</p>  A hand holds a yellow and black electronic device against a white wall. The device has a screen and several buttons, and is labeled "EQUPO DE DETECCIÓN DE CONDICIONES ATMOSFÉRICAS".
<p>Foto 21) Botiquines de emergencia en campamento</p>  A sign on a wooden post reads "ADVERTENCIA SERPIENTES VENENOSAS" with a snake icon. It is placed near a red pickup truck and a silver car on a dirt road.	<p>Foto 22) Equipo de detección de condiciones atmosféricas</p>  A wooden sign on a post reads "ADVERTENCIA SERPIENTES VENENOSAS" with a snake icon. It is placed near a green shipping container and a wooden staircase.
<p>Foto 23) Letrero de protección de los recursos naturales</p>	<p>Foto 24) Letrero de protección de los recursos naturales</p>

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

	
<p>Foto 25) Letrero informativo de advertencia</p> 	<p>Foto 26) Rotulación referente a actividades</p> 
<p>Foto 27) Vías de evacuación señalizadas</p>	<p>Foto 28) Operaciones de carga, descarga y transporte del material</p>
<p>Foto 29) Regular el ingreso y salida de equipo</p> 	<p>Foto 30) Regular el ingreso y salida de equipo</p> 
<p>Foto 31) Extintores en oficinas</p>	<p>Foto 32) Extintores en campo</p>

Anexo Fotográfico Informe No. 3
Resolución 003-2018 PTAP Gamboa

																																											
<p>Foto 33) Material acopiado</p> 	<p>Foto 34) Baños portátiles en campo</p> 																																										
<p>Foto 35) Baños portátiles en campo</p>	<p>Foto 36) Procedimientos legibles en caso de incidentes o accidentes</p>																																										
<p>EN CASO DE URGENCIAS</p> <table border="1"> <tr> <td>AMBULANCIAS</td> <td>6855-2343</td> </tr> <tr> <td>AMBULANCIAS ALPHA</td> <td>6855-2343</td> </tr> <tr> <td>AMBULANCIA COROZAL, SISED</td> <td>512-9783</td> </tr> <tr> <td>911</td> <td>911</td> </tr> <tr> <td>SISTEMA DE EMERGENCIAS MEDICAS</td> <td>911</td> </tr> <tr> <td>POL. DON ALEJANDRO DE LA GUARDIA HIJO EN BETHANA</td> <td>503-1213</td> </tr> <tr> <td>CRUZ ROJA NACIONAL - ALBROOK</td> <td>315-1179</td> </tr> <tr> <td>CENTRO DE CONTROL DE EMERGENCIAS AUTORIZADO DEL CANAL DE PANAMA</td> <td>276-3669</td> </tr> <tr> <td>EMERGENCIAS MÉDICAS - HOSPITALES</td> <td></td> </tr> <tr> <td>CENTRO DE SALUD DE PARASO MINSA</td> <td>232-4852</td> </tr> <tr> <td>HOSPITAL SAN MIGUEL ARANGEN</td> <td>523-6950</td> </tr> <tr> <td>C. H. DR. ARNUFO ARIAS MADRID</td> <td>503-6685</td> </tr> <tr> <td>POLICIA NACIONAL</td> <td></td> </tr> <tr> <td>POLICIA NACIONAL - GAMBOA</td> <td>511-7000 / 104</td> </tr> <tr> <td>ATTI / ALBROOK</td> <td>502-4591</td> </tr> <tr> <td>BOMBEROS</td> <td></td> </tr> <tr> <td>BOMBEROS ESTACION PEDRO MIGUEL</td> <td>232-4180</td> </tr> <tr> <td>CUERPO DE BOMBEROS</td> <td>512-4148</td> </tr> <tr> <td>CUERPO DE BOMBEROS GAMBOA</td> <td>276-6658</td> </tr> <tr> <td>PROTECCION CIVIL - SINAPROC</td> <td>335</td> </tr> <tr> <td>RESCATE ANIMAL</td> <td>503-2003</td> </tr> </table>	AMBULANCIAS	6855-2343	AMBULANCIAS ALPHA	6855-2343	AMBULANCIA COROZAL, SISED	512-9783	911	911	SISTEMA DE EMERGENCIAS MEDICAS	911	POL. DON ALEJANDRO DE LA GUARDIA HIJO EN BETHANA	503-1213	CRUZ ROJA NACIONAL - ALBROOK	315-1179	CENTRO DE CONTROL DE EMERGENCIAS AUTORIZADO DEL CANAL DE PANAMA	276-3669	EMERGENCIAS MÉDICAS - HOSPITALES		CENTRO DE SALUD DE PARASO MINSA	232-4852	HOSPITAL SAN MIGUEL ARANGEN	523-6950	C. H. DR. ARNUFO ARIAS MADRID	503-6685	POLICIA NACIONAL		POLICIA NACIONAL - GAMBOA	511-7000 / 104	ATTI / ALBROOK	502-4591	BOMBEROS		BOMBEROS ESTACION PEDRO MIGUEL	232-4180	CUERPO DE BOMBEROS	512-4148	CUERPO DE BOMBEROS GAMBOA	276-6658	PROTECCION CIVIL - SINAPROC	335	RESCATE ANIMAL	503-2003	
AMBULANCIAS	6855-2343																																										
AMBULANCIAS ALPHA	6855-2343																																										
AMBULANCIA COROZAL, SISED	512-9783																																										
911	911																																										
SISTEMA DE EMERGENCIAS MEDICAS	911																																										
POL. DON ALEJANDRO DE LA GUARDIA HIJO EN BETHANA	503-1213																																										
CRUZ ROJA NACIONAL - ALBROOK	315-1179																																										
CENTRO DE CONTROL DE EMERGENCIAS AUTORIZADO DEL CANAL DE PANAMA	276-3669																																										
EMERGENCIAS MÉDICAS - HOSPITALES																																											
CENTRO DE SALUD DE PARASO MINSA	232-4852																																										
HOSPITAL SAN MIGUEL ARANGEN	523-6950																																										
C. H. DR. ARNUFO ARIAS MADRID	503-6685																																										
POLICIA NACIONAL																																											
POLICIA NACIONAL - GAMBOA	511-7000 / 104																																										
ATTI / ALBROOK	502-4591																																										
BOMBEROS																																											
BOMBEROS ESTACION PEDRO MIGUEL	232-4180																																										
CUERPO DE BOMBEROS	512-4148																																										
CUERPO DE BOMBEROS GAMBOA	276-6658																																										
PROTECCION CIVIL - SINAPROC	335																																										
RESCATE ANIMAL	503-2003																																										
<p>Foto 37) Procedimientos legibles en caso de incidentes o accidentes</p>	<p>Foto 38) Letrero en el acceso a Cerro Tigre</p>																																										