

Anexo No. 1
Fotografías del área de influencia del proyecto

 A photograph showing a dirt road curving to the right, bordered by a tall concrete wall on the left. Two utility poles stand near the wall. The ground is covered in sparse grass and dirt.	 A photograph of a dirt road that has become very muddy and water-filled with large puddles. It appears to be a rural or semi-rural area with some houses visible in the background.
Camino hacia Guabas arriba, al Oeste el Residencial La Villas y al Este del camino, el proyecto de desarrollo de interés social “Hacienda El Mirador – Los Bambú” (Izquierda). Camino de acceso al proyecto y vía hacia el poblado de Guabas Arriba, en época de lluvia. No ha continuado su construcción por la pandemia Covid-19. (Derecha).	
 A photograph of a field filled with dense green vegetation, likely grasses and low shrubs. The sky above is overcast.	 A photograph of a field with tall, dry, brownish grass. Some green vegetation is visible in the background under an overcast sky.
 A photograph of a field with a mix of green and brown vegetation, suggesting a transition between different plant communities or stages of growth.	 A photograph of a field dominated by tall, green grasses and some scattered trees in the background under a cloudy sky.
Vegetación en el área del proyecto. La vegetación arbórea, se concentra dentro de la servidumbre del Río Las Guabas.	




Vegetación arbórea, en la colindancia al Río Las Guabas.



Vegetación de gramíneas dentro del proyecto.



Transporte público hacia Guabas Arriba – Antón, por el camino colindante con el proyecto al Oeste.



Río Las Guabas, en época de lluvia. Se observa su cauce y márgenes con suelos franco arenosos, por lo que, el color del agua, es blanco.



Toma de la muestra de agua superficial de línea base, en el río Las Guabas.